

Release Note LS-200 v2.8.6.24

Bug Fixed

- Fix "RS-232/TCP cannot get layout ID when layout is set to ID #0"
- Enable HTTP port under HTTPS mode
- Mute all audio sources in pause status
- Add CPU usage monitor on Web Director
- Modify configuration importing, config. File in same model but older generation could be imported onto the new gen. version (e.g. config. From 2.6.0.22 can be imported on v2.8.0.22 LS-300)
- Fix "Videos contain bookmarks cannot be processed on Panopto"
- Add CPU usage monitor on GUI Settings -> Configuration Status
- Fix "Display gets stuck in loading scene after applying any video input's signal type to "None"
- Fix "The Mixed video turn to complete black after setting the layout to ID 0 and applying video related configurations"
- Fix "RS-232/TCP get WAN IP response incorrect when network is set to fixed IP (always gets 192.168.11.154)"
- Fix "Web service error after adding ONVIF cameras which contains non-UTF8 string (ex A-TC01)"
- Fix "RS-232/TCP layout notification failed when layout was set to ID 0"
- Fix "String error in German"
- Fix "RS-232/TCP set camera preset command returns success code when the preset ID called is not available"