

Release Note LS-400 v2.8.1.24

Bug Fixed

- Fix “RS-232/TCP cannot get layout ID when layout is set to ID #0”
- Enable HTTP port under HTTPS mode
- Mute all audio sources in pause status
- Add CPU usage monitor on Web Director
- Modify configuration importing, config. File in same model but older generation could be imported onto the new gen. version (e.g. config. From 2.6.0.22 can be imported on v2.8.0.22 LS-300)
- Fix “Videos contain bookmarks cannot be processed on Panopto”