

Release Note LS-860 v5.3.0.7

Bug Fixed

- Mute all audio sources in pause state
- Enable HTTP port under HTTPS mode
- Fix “No audio output on HDMI out”
- Fix “Cannot set RTP stream URL in the web page”