
Release Note KL-3/KL-3WT v2.8.7.22

New Features

Item	NEW Features
WEB	
Director	CPU loading indicator
GUI	
GUI/Settings	Remove the “Touch HID Calibration” button
GUI/Settings/Setting Status	CPU loading indicator

- Notice: During the firmware update progress, please always keep the power on to prevent permanent system unstable or damage.